Fujitsu Lifebook Stylistic Q584 USB port Replacement

Remove the USB port from the Fujitsu Lifebook Stylistic Q584.

Written By: Spencer Bacon

This document was generated on 2020-11-23 02:14:59 PM (MST).

INTRODUCTION

We will walk through removal the USB port from the Fujitsu Lifebook Stylistic Q584.

🔧 TOOLS:

- Phillips #00 Screwdriver (1)
- iFixit Opening Tools (1)
- Phillips #1 Screwdriver (1)
- Phillips #000 Screwdriver (1)

This document was generated on 2020-11-23 02:14:59 PM (MST).

www.iFixit.com

Step 1 — Back Case

- Remove the white sticker covering the screws *(if applicable)*.

- Use the PH1 screwdriver to remove the four 2 mm screws from the the backside of the device.

Step 2

- Insert the plastic opening tool along the seam of the back case.

- Gently slide the plastic opening tool along the entire seam popping the clips free.

www.iFixit.com

Step 3

- Carefully lift the back case and remove the smartcard ribbon from the motherboard.

Step 4 — Inner Back Shield

- Remove the ten 3mm screws with a PH00 screwdriver from the shield.

www.iFixit.com

Step 5

- Remove the grey docking station port cover.

Step 6

- Gently slide the plastic opening tool along the entire seam popping the clips free.

This document was generated on 2020-11-23 02:14:59 PM (MST).

Step 7

● Lift the shield away from the device and remove the fingerprint scanner's ribbon from the motherboard.

Step 8 — USB port

● Remove 2mm screw with a PH1 screwdriver from USB board

Step 9

- Disconnect USB periphery ribbon from motherboard

Step 10

- Pull USB board up to remove.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-23 02:14:59 PM (MST).