# iFIXIT

Bionaire BAP 600 Transformer Replacement

Bionaire BAP 600 Transformer Replacement

Written By: Alexander Tarancon

www.iFixit.com

INTRODUCTION

Bionaire BAP 600 Transformer Replacement

🔧 TOOLS:

- Phillips #0 Screwdriver (1)

## Step 1 — Control Board

- Unplug 7 pin connector

Step 2

- Unplug 2 pin wires which connects the front LED's.

This document was generated on 2020-11-22 07:39:12 PM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 3 of 6

Step 3

- Remove two screws

Step 4

- Unplug pins

- Use scissors to cut zip ties

Step 5

- Unplug rest of pin connections

- Remove Neutral and Hot wires

- They are the two black wires

- Pull them out

Step 6

- Unscrew two screws

- Inspect capacitor for any bulges (if it has a bulge , it means it is need to be replaced)

- Check for burnt solder in the back of circuit board

This document was generated on 2020-11-22 07:39:12 PM (MST).

Step 7 — Transformer

- Use screwdriver to remove screws

To reassemble your device, follow these instructions in reverse order.