


2001-2006 Mini Cooper MAP Sensor Replacement

This video guide will teach you how to replace a MAP sensor in a 2001-2006 Mini Cooper. The instruction ends at 11:41 and continues on to the thermostat.

Written By: Sydtracked



This document was generated on 2021-01-08 06:30:57 PM (MST).



TOOLS:

- 10mm Wrench (1)
- Flathead 3/32" or 2.5 mm Screwdriver (1)
- 1/4" Ratchet Extension (1)
- 3mm Hex Key (or Bit) (1)
- 10mm Socket (1)
- Socket Wrench (1)



MAP Sensor (1)

To reassemble your device, follow these instructions in reverse order.