



Lenovo ThinkPad T431S Screen Replacement

This guide will show you how to locate and replace the Lenovo T431s screen.

Written By: Christine Portanova



INTRODUCTION


This guide will show you how to locate and replace the Lenovo T431s screen. The screen is what gives your visuals on your computer. If you have a blotchy screen, poor visuals, or physical screen damage, you might need to replace your screen.

TOOLS:

- [iFixit Opening Tools](#) (1)
 - [Phillips #1 Screwdriver](#) (1)
 - [Jimmy](#) (1)
-

Step 1 — Screen



 Remember before starting any disassembly, to prevent electric shock or harm, disconnect from any external power source and make sure device is powered off.

- Use the Jimmy tool to remove the screen bezel with a gentle prying motion.

Step 2




- Remove the four 3.0 mm screws in the four corners of the screen with a Phillips #1 screwdriver bit.
- While removing the screws, pry the screen off with an opening tool.

⚠ If your screen is cracked, use caution, as there will be broken glass or sharp parts.

Step 3



- Lift screen off of top panel to reveal LCD power plug/connector.
 - There will be a wire attaching the screen to the rest of the device.
 - Remove the tape on the wire so you can unplug the connection, pulling upwards.
-  Information about disposal of your damaged screen can be found at [E-Waste Recycling](#)

To reassemble your device, follow these instructions in reverse order.